

**CAAQMS-2, Premises of M/s. Satpuda Thermal Power Station, Sarni, Betul  
(M.P.)**

**(August - 2018)**

<b>Sr.no</b>	<b>DATE</b>	<b>AQI No.</b>	<b>AQI Code</b>	<b>AQI Status</b>	<b>Prominent Pollutant</b>
1	01/08/2018	1094		Severe	PM <sub>10</sub>
2	02/08/2018	1094		Severe	PM <sub>10</sub>
3	03/08/2018	1094		Severe	PM <sub>10</sub>
4	04/08/2018	1094		Severe	PM <sub>10</sub>
5	05/08/2018	1094		Severe	PM <sub>10</sub>
6	06/08/2018	1094		Severe	PM <sub>10</sub>
7	07/08/2018	1094		Severe	PM <sub>10</sub>
8	08/08/2018	1094		Severe	PM <sub>10</sub>
9	09/08/2018	1094		Severe	PM <sub>10</sub>
10	10/08/2018	1094		Severe	PM <sub>10</sub>
11	11/08/2018	1094		Severe	PM <sub>10</sub>
12	12/08/2018	1094		Severe	PM <sub>10</sub>
13	13/08/2018	1094		Severe	PM <sub>10</sub>
14	14/08/2018	1094		Severe	PM <sub>10</sub>
15	15/08/2018	1068		Severe	PM <sub>2.5</sub>
16	16/08/2018	633		Severe	PM <sub>10</sub>
17	17/08/2018	I.D	-	-	-
18	18/08/2018	I.D	-	-	-
19	19/08/2018	I.D	-	-	-
20	20/08/2018	I.D	-	-	-
21	21/08/2018	I.D	-	-	-
22	22/08/2018	I.D	-	-	-
23	23/08/2018	I.D	-	-	-
24	24/08/2018	I.D	-	-	-
25	25/08/2018	I.D	-	-	-
26	26/08/2018	I.D	-	-	-
27	27/08/2018	I.D	-	-	-
28	28/08/2018	I.D	-	-	-
29	29/08/2018	I.D	-	-	-
30	30/08/2018	I.D	-	-	-
31	31/08/2018	I.D	-	-	-

I.D. – Insufficient Data