

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-1, Sarni, Betul
(M.P.)**

(August - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/08/2019	13		Good	PM ₁₀
2	02/08/2019	26		Good	PM ₁₀
3	03/08/2019	20		Good	PM ₁₀
4	04/08/2019	14		Good	PM ₁₀
5	05/08/2019	20		Good	PM ₁₀
6	06/08/2019	26		Good	PM ₁₀
7	07/08/2019	26		Good	PM ₁₀
8	08/08/2019	14		Good	PM ₁₀
9	09/08/2019	9		Good	PM ₁₀
10	10/08/2019	37		Good	PM ₁₀
11	11/08/2019	47		Good	PM ₁₀
12	12/08/2019	64		Satisfactory	PM ₁₀
13	13/08/2019	54		Satisfactory	PM ₁₀
14	14/08/2019	32		Good	PM ₁₀
15	15/08/2019	30		Good	PM ₁₀
16	16/08/2019	25		Good	PM ₁₀
17	17/08/2019	24		Good	PM ₁₀
18	18/08/2019	No Data	-	-	-
19	19/08/2019	No Data	-	-	-
20	20/08/2019	No Data	-	-	-
21	21/08/2019	35		Good	PM ₁₀
22	22/08/2019	27		Good	PM ₁₀
23	23/08/2019	31		Good	PM ₁₀
24	24/08/2019	27		Good	PM ₁₀
25	25/08/2019	20		Good	PM ₁₀
26	26/08/2019	7		Good	PM ₁₀
27	27/08/2019	8		Good	PM ₁₀
28	28/08/2019	25		Good	PM ₁₀
29	29/08/2019	40		Good	PM ₁₀
30	30/08/2019	33		Good	PM ₁₀
31	31/08/2019	38		Good	PM ₁₀