

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-2, Sarni, Betul
(M.P.)**

(August - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/08/2019	61		Satisfactory	CO
2	02/08/2019	61		Satisfactory	CO
3	03/08/2019	301		Very Poor	PM _{2.5}
4	04/08/2019	226		Poor	PM _{2.5}
5	05/08/2019	317		Very Poor	PM _{2.5}
6	06/08/2019	269		Poor	PM _{2.5}
7	07/08/2019	202		Poor	PM _{2.5}
8	08/08/2019	163		Moderate	PM _{2.5}
9	09/08/2019	72		Satisfactory	PM _{2.5}
10	10/08/2019	226		Poor	PM _{2.5}
11	11/08/2019	257		Poor	PM _{2.5}
12	12/08/2019	211		Poor	PM _{2.5}
13	13/08/2019	208		Poor	PM _{2.5}
14	14/08/2019	59		Satisfactory	CO
15	15/08/2019	60		Satisfactory	CO
16	16/08/2019	62		Satisfactory	CO
17	17/08/2019	64		Satisfactory	CO
18	18/08/2019	No Data	-	-	-
19	19/08/2019	No Data	-	-	-
20	20/08/2019	No Data	-	-	-
21	21/08/2019	338		Very Poor	PM _{2.5}
22	22/08/2019	71		Satisfactory	CO
23	23/08/2019	71		Satisfactory	CO
24	24/08/2019	72		Satisfactory	CO
25	25/08/2019	72		Satisfactory	CO
26	26/08/2019	73		Satisfactory	CO
27	27/08/2019	73		Satisfactory	CO
28	28/08/2019	73		Satisfactory	CO
29	29/08/2019	74		Satisfactory	CO
30	30/08/2019	75		Satisfactory	CO
31	31/08/2019	75		Satisfactory	CO