

**Premises of M/s. Hindalco Industries Ltd. (Captive power unit), CAAQMS-2,
Singrauli - Sidhi Road, P.O. Bargawan, Dist. Singrauli (M.P.)**

(December - 2018)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/12/2018	50		Good	PM ₁₀
2	02/12/2018	50		Good	PM ₁₀
3	03/12/2018	49		Good	PM ₁₀
4	04/12/2018	46		Good	PM ₁₀
5	05/12/2018	54		Satisfactory	PM ₁₀
6	06/12/2018	57		Satisfactory	PM ₁₀
7	07/12/2018	57		Satisfactory	PM ₁₀
8	08/12/2018	50		Good	PM ₁₀
9	09/12/2018	57		Satisfactory	PM ₁₀
10	10/12/2018	67		Satisfactory	PM ₁₀
11	11/12/2018	337		Very Poor	PM ₁₀
12	12/12/2018	81		Satisfactory	PM ₁₀
13	13/12/2018	91		Satisfactory	PM ₁₀
14	14/12/2018	60		Satisfactory	PM ₁₀
15	15/12/2018	44		Good	PM ₁₀
16	16/12/2018	No Data	-	-	-
17	17/12/2018	61		Satisfactory	PM ₁₀
18	18/12/2018	30		Good	PM ₁₀
19	19/12/2018	43		Good	PM ₁₀
20	20/12/2018	52		Satisfactory	PM ₁₀
21	21/12/2018	55		Satisfactory	PM ₁₀
22	22/12/2018	63		Satisfactory	PM ₁₀
23	23/12/2018	66		Satisfactory	PM ₁₀
24	24/12/2018	57		Satisfactory	PM ₁₀
25	25/12/2018	56		Satisfactory	PM ₁₀
26	26/12/2018	48		Good	PM ₁₀
27	27/12/2018	49		Good	PM ₁₀
28	28/12/2018	49		Good	PM ₁₀
29	29/12/2018	51		Satisfactory	PM ₁₀
30	30/12/2018	69		Satisfactory	PM ₁₀
31	31/12/2018	73		Satisfactory	PM ₁₀