

**Premises of M/s Trimula Industries Ltd. CAAQMS-1, Post: Godwali, Teh. Devssar,
Dist. Singrauli (M.P.)**

(February - 2018)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/02/2018	270		Poor	PM ₁₀
2	02/02/2018	476		Severe	PM ₁₀
3	03/02/2018	407		Severe	PM ₁₀
4	04/02/2018	420		Severe	PM ₁₀
5	05/02/2018	373		Very Poor	PM ₁₀
6	06/02/2018	312		Very Poor	PM ₁₀
7	07/02/2018	297		Poor	PM ₁₀
8	08/02/2018	363		Very Poor	PM ₁₀
9	09/02/2018	542		Severe	PM ₁₀
10	10/02/2018	556		Severe	PM ₁₀
11	11/02/2018	460		Severe	PM ₁₀
12	12/02/2018	313		Very Poor	PM ₁₀
13	13/02/2018	88		Satisfactory	PM ₁₀
14	14/02/2018	220		Poor	PM ₁₀
15	15/02/2018	266		Poor	PM ₁₀
16	16/02/2018	330		Very Poor	PM ₁₀
17	17/02/2018	496		Severe	PM ₁₀
18	18/02/2018	246		Poor	PM ₁₀
19	19/02/2018	336		Very Poor	PM ₁₀
20	20/02/2018	433		Severe	PM ₁₀
21	21/02/2018	879		Severe	PM ₁₀
22	22/02/2018	1107		Severe	PM ₁₀
23	23/02/2018	1107		Severe	PM ₁₀
24	24/02/2018	1107		Severe	PM ₁₀
25	25/02/2018	654		Severe	PM ₁₀
26	26/02/2018	426		Severe	PM ₁₀
27	27/02/2018	550		Severe	PM ₁₀
28	28/02/2018	591		Severe	PM ₁₀