

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-2, Sarni, Betul
(M.P.)**

(July - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/07/2019	I.D.	-	-	-
2	02/07/2019	I.D.	-	-	-
3	03/07/2019	I.D.	-	-	-
4	04/07/2019	I.D.	-	-	-
5	05/07/2019	I.D.	-	-	-
6	06/07/2019	I.D.	-	-	-
7	07/07/2019	I.D.	-	-	-
8	08/07/2019	I.D.	-	-	-
9	09/07/2019	I.D.	-	-	-
10	10/07/2019	I.D.	-	-	-
11	11/07/2019	I.D.	-	-	-
12	12/07/2019	I.D.	-	-	-
13	13/07/2019	I.D.	-	-	-
14	14/07/2019	I.D.	-	-	-
15	15/07/2019	I.D.	-	-	-
16	16/07/2019	I.D.	-	-	-
17	17/07/2019	I.D.	-	-	-
18	18/07/2019	I.D.	-	-	-
19	19/07/2019	I.D.	-	-	-
20	20/07/2019	I.D.	-	-	-
21	21/07/2019	I.D.	-	-	-
22	22/07/2019	I.D.	-	-	-
23	23/07/2019	I.D.	-	-	-
24	24/07/2019	I.D.	-	-	-
25	25/07/2019	I.D.	-	-	-
26	26/07/2019	I.D.	-	-	-
27	27/07/2019	I.D.	-	-	-
28	28/07/2019	I.D.	-	-	-
29	29/07/2019	I.D.	-	-	-
30	30/07/2019	I.D.	-	-	-
31	31/07/2019	I.D.	-	-	-

I.D. – Insufficient Data