

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-4, Sarni, Betul
(M.P.)**

(July - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/07/2019	70		Satisfactory	PM ₁₀
2	02/07/2019	69		Satisfactory	PM ₁₀
3	03/07/2019	69		Satisfactory	SO ₂
4	04/07/2019	68		Satisfactory	SO ₂
5	05/07/2019	68		Satisfactory	SO ₂
6	06/07/2019	68		Satisfactory	SO ₂
7	07/07/2019	67		Satisfactory	PM ₁₀
8	08/07/2019	67		Satisfactory	PM ₁₀
9	09/07/2019	67		Satisfactory	PM ₁₀
10	10/07/2019	67		Satisfactory	PM ₁₀
11	11/07/2019	68		Satisfactory	PM ₁₀
12	12/07/2019	68		Satisfactory	PM ₁₀
13	13/07/2019	68		Satisfactory	PM ₁₀
14	14/07/2019	27		Good	PM ₁₀
15	15/07/2019	75		Satisfactory	PM ₁₀
16	16/07/2019	69		Satisfactory	PM ₁₀
17	17/07/2019	70		Satisfactory	PM ₁₀
18	18/07/2019	71		Satisfactory	PM ₁₀
19	19/07/2019	71		Satisfactory	PM ₁₀
20	20/07/2019	72		Satisfactory	PM ₁₀
21	21/07/2019	72		Satisfactory	PM ₁₀
22	22/07/2019	72		Satisfactory	SO ₂
23	23/07/2019	73		Satisfactory	PM ₁₀
24	24/07/2019	72		Satisfactory	PM ₁₀
25	25/07/2019	79		Satisfactory	PM ₁₀
26	26/07/2019	No Data	-	-	-
27	27/07/2019	No Data	-	-	-
28	28/07/2019	No Data	-	-	-
29	29/07/2019	No Data	-	-	-
30	30/07/2019	No Data	-	-	-
31	31/07/2019	840		Severe	PM _{2.5}