

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-2, Sarni, Betul
(M.P.)**

(June - 2020)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/06/2020	105		Moderate	CO
2	02/06/2020	105		Moderate	CO
3	03/06/2020	105		Moderate	CO
4	04/06/2020	105		Moderate	CO
5	05/06/2020	460		Severe	PM _{2.5}
6	06/06/2020	965		Severe	PM _{2.5}
7	07/06/2020	No Data	-	-	-
8	08/06/2020	965		Severe	PM _{2.5}
9	09/06/2020	965		Severe	PM _{2.5}
10	10/06/2020	811		Severe	PM _{2.5}
11	11/06/2020	112		Moderate	PM _{2.5}
12	12/06/2020	105		Moderate	CO
13	13/06/2020	547		Severe	PM _{2.5}
14	14/06/2020	No Data	-	-	-
15	15/06/2020	599		Severe	PM _{2.5}
16	16/06/2020	458		Severe	PM _{2.5}
17	17/06/2020	520		Severe	PM _{2.5}
18	18/06/2020	517		Severe	PM _{2.5}
19	19/06/2020	434		Severe	PM _{2.5}
20	20/06/2020	444		Severe	PM _{2.5}
21	21/06/2020	443		Severe	PM _{2.5}
22	22/06/2020	368		Very Poor	PM _{2.5}
23	23/06/2020	103		Moderate	CO
24	24/06/2020	456		Severe	PM _{2.5}
25	25/06/2020	416		Severe	PM _{2.5}
26	26/06/2020	103		Moderate	CO
27	27/06/2020	357		Very Poor	PM _{2.5}
28	28/06/2020	109		Moderate	PM _{2.5}
29	29/06/2020	148		Moderate	PM _{2.5}
30	30/06/2020	114		Moderate	PM _{2.5}