

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-3, Sarni, Betul  
(M.P.)**

**(November - 2018)**

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/11/2018	I.D.	-	-	-
2	02/11/2018	I.D.	-	-	-
3	03/11/2018	I.D.	-	-	-
4	04/11/2018	I.D.	-	-	-
5	05/11/2018	I.D.	-	-	-
6	06/11/2018	I.D.	-	-	-
7	07/11/2018	I.D.	-	-	-
8	08/11/2018	I.D.	-	-	-
9	09/11/2018	221		Poor	PM <sub>10</sub>
10	10/11/2018	1094		Severe	PM <sub>10</sub>
11	11/11/2018	1094		Severe	PM <sub>10</sub>
12	12/11/2018	1094		Severe	PM <sub>10</sub>
13	13/11/2018	1094		Severe	PM <sub>10</sub>
14	14/11/2018	1094		Severe	PM <sub>10</sub>
15	15/11/2018	1094		Severe	PM <sub>10</sub>
16	16/11/2018	1094		Severe	PM <sub>10</sub>
17	17/11/2018	1094		Severe	PM <sub>10</sub>
18	18/11/2018	1094		Severe	PM <sub>10</sub>
19	19/11/2018	1094		Severe	PM <sub>10</sub>
20	20/11/2018	1094		Severe	PM <sub>10</sub>
21	21/11/2018	1094		Severe	PM <sub>10</sub>
22	22/11/2018	1094		Severe	PM <sub>10</sub>
23	23/11/2018	1094		Severe	PM <sub>10</sub>
24	24/11/2018	1094		Severe	PM <sub>10</sub>
25	25/11/2018	1094		Severe	PM <sub>10</sub>
26	26/11/2018	1094		Severe	PM <sub>10</sub>
27	27/11/2018	1094		Severe	PM <sub>10</sub>
28	28/11/2018	1094		Severe	PM <sub>10</sub>
29	29/11/2018	1094		Severe	PM <sub>10</sub>
30	30/11/2018	1094		Severe	PM <sub>10</sub>
		-	-	-	-