

**CAAQMS-4, Premises of M/s. Satpuda Thermal Power Station, Sarni, Betul  
(M.P.)**

**(September - 2018)**

<b>Sr.no</b>	<b>DATE</b>	<b>AQI No.</b>	<b>AQI Code</b>	<b>AQI Status</b>	<b>Prominent Pollutant</b>
1	01/09/2018	66		Satisfactory	PM <sub>10</sub>
2	02/09/2018	27		Good	PM <sub>10</sub>
3	03/09/2018	24		Good	PM <sub>10</sub>
4	04/09/2018	28		Good	PM <sub>10</sub>
5	05/09/2018	47		Good	PM <sub>10</sub>
6	06/09/2018	35		Good	PM <sub>10</sub>
7	07/09/2018	33		Good	PM <sub>10</sub>
8	08/09/2018	7		Good	PM <sub>10</sub>
9	09/09/2018	No Data	-	-	-
10	10/09/2018	No Data	-	-	-
11	11/09/2018	No Data	-	-	-
12	12/09/2018	No Data	-	-	-
13	13/09/2018	No Data	-	-	-
14	14/09/2018	152		Moderate	NO <sub>x</sub>
15	15/09/2018	194		Moderate	NO <sub>x</sub>
16	16/09/2018	197		Moderate	NO <sub>x</sub>
17	17/09/2018	197		Moderate	NO <sub>x</sub>
18	18/09/2018	192		Moderate	NO <sub>x</sub>
19	19/09/2018	198		Moderate	NO <sub>x</sub>
20	20/09/2018	208		Poor	NO <sub>x</sub>
21	21/09/2018	229		Poor	NO <sub>x</sub>
22	22/09/2018	324		Very Poor	NO <sub>x</sub>
23	23/09/2018	179		Moderate	NO <sub>x</sub>
24	24/09/2018	206		Poor	NO <sub>x</sub>
25	25/09/2018	241		Poor	NO <sub>x</sub>
26	26/09/2018	252		Poor	NO <sub>x</sub>
27	27/09/2018	236		Poor	NO <sub>x</sub>
28	28/09/2018	174		Moderate	NO <sub>x</sub>
29	29/09/2018	168		Moderate	NO <sub>x</sub>
30	30/09/2018	219		Poor	NO <sub>x</sub>
		-	-	-	-