

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-1, Sarni, Betul
(M.P.)**

(September - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/09/2019	34		Good	PM ₁₀
2	02/09/2019	23		Good	PM ₁₀
3	03/09/2019	25		Good	PM ₁₀
4	04/09/2019	23		Good	PM ₁₀
5	05/09/2019	25		Good	PM ₁₀
6	06/09/2019	25		Good	PM ₁₀
7	07/09/2019	984		Severe	PM ₁₀
8	08/09/2019	610		Severe	PM ₁₀
9	09/09/2019	11		Good	PM ₁₀
10	10/09/2019	12		Good	PM ₁₀
11	11/09/2019	19		Good	PM ₁₀
12	12/09/2019	19		Good	PM ₁₀
13	13/09/2019	10		Good	PM ₁₀
14	14/09/2019	12		Good	PM ₁₀
15	15/09/2019	17		Good	PM ₁₀
16	16/09/2019	26		Good	PM ₁₀
17	17/09/2019	29		Good	PM ₁₀
18	18/09/2019	25		Good	PM ₁₀
19	19/09/2019	86		Satisfactory	PM ₁₀
20	20/09/2019	43		Good	PM ₁₀
21	21/09/2019	47		Good	PM ₁₀
22	22/09/2019	46		Good	PM ₁₀
23	23/09/2019	42		Good	PM ₁₀
24	24/09/2019	41		Good	PM ₁₀
25	25/09/2019	35		Good	PM ₁₀
26	26/09/2019	43		Good	PM ₁₀
27	27/09/2019	21		Good	PM ₁₀
28	28/09/2019	47		Good	PM ₁₀
29	29/09/2019	77		Satisfactory	PM ₁₀
30	30/09/2019	44		Good	PM ₁₀
		-	-	-	-