

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-2, Sarni, Betul
(M.P.)**

(September - 2019)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/09/2019	76		Satisfactory	CO
2	02/09/2019	133		Moderate	PM ₁₀
3	03/09/2019	76		Satisfactory	CO
4	04/09/2019	76		Satisfactory	CO
5	05/09/2019	258		Poor	PM ₁₀
6	06/09/2019	No Data	-	-	-
7	07/09/2019	No Data	-	-	-
8	08/09/2019	No Data	-	-	-
9	09/09/2019	No Data	-	-	-
10	10/09/2019	No Data	-	-	-
11	11/09/2019	No Data	-	-	-
12	12/09/2019	No Data	-	-	-
13	13/09/2019	No Data	-	-	-
14	14/09/2019	No Data	-	-	-
15	15/09/2019	No Data	-	-	-
16	16/09/2019	No Data	-	-	-
17	17/09/2019	No Data	-	-	-
18	18/09/2019	No Data	-	-	-
19	19/09/2019	276		Poor	PM _{2.5}
20	20/09/2019	76		Satisfactory	CO
21	21/09/2019	956		Severe	PM ₁₀
22	22/09/2019	77		Satisfactory	CO
23	23/09/2019	77		Satisfactory	CO
24	24/09/2019	301		Very Poor	PM _{2.5}
25	25/09/2019	77		Satisfactory	CO
26	26/09/2019	76		Satisfactory	CO
27	27/09/2019	76		Satisfactory	CO
28	28/09/2019	77		Satisfactory	CO
29	29/09/2019	77		Satisfactory	CO
30	30/09/2019	78		Satisfactory	CO
		-	-	-	-