

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-2, Sarni, Betul
(M.P.)**

(September - 2020)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/09/2020	I.D.	-	-	-
2	02/09/2020	I.D.	-	-	-
3	03/09/2020	I.D.	-	-	-
4	04/09/2020	I.D.	-	-	-
5	05/09/2020	20		Good	SO ₂
6	06/09/2020	I.D.	-	-	-
7	07/09/2020	I.D.	-	-	-
8	08/09/2020	I.D.	-	-	-
9	09/09/2020	I.D.	-	-	-
10	10/09/2020	I.D.	-	-	-
11	11/09/2020	I.D.	-	-	-
12	12/09/2020	I.D.	-	-	-
13	13/09/2020	I.D.	-	-	-
14	14/09/2020	I.D.	-	-	-
15	15/09/2020	I.D.	-	-	-
16	16/09/2020	I.D.	-	-	-
17	17/09/2020	I.D.	-	-	-
18	18/09/2020	I.D.	-	-	-
19	19/09/2020	I.D.	-	-	-
20	20/09/2020	I.D.	-	-	-
21	21/09/2020	I.D.	-	-	-
22	22/09/2020	I.D.	-	-	-
23	23/09/2020	47		Good	PM ₁₀
24	24/09/2020	152		Moderate	NO _x
25	25/09/2020	263		Poor	NO _x
26	26/09/2020	276		Poor	NO _x
27	27/09/2020	277		Poor	NO _x
28	28/09/2020	256		Poor	NO _x
29	29/09/2020	243		Poor	NO _x
30	30/09/2020	253		Poor	NO _x

I.D. – Insufficient Data