

**Premises of M/s. Satpuda Thermal Power Station, CAAQMS-4, Sarni, Betul
(M.P.)**

(September - 2020)

Sr.No.	Date	AQI No.	AQI Code	AQI Status	Prominent Pollutant
1	01/09/2020	I.D.	-	-	-
2	02/09/2020	I.D.	-	-	-
3	03/09/2020	I.D.	-	-	-
4	04/09/2020	I.D.	-	-	-
5	05/09/2020	I.D.	-	-	-
6	06/09/2020	I.D.	-	-	-
7	07/09/2020	I.D.	-	-	-
8	08/09/2020	I.D.	-	-	-
9	09/09/2020	I.D.	-	-	-
10	10/09/2020	No Data	-	-	-
11	11/09/2020	No Data	-	-	-
12	12/09/2020	No Data	-	-	-
13	13/09/2020	No Data	-	-	-
14	14/09/2020	No Data	-	-	-
15	15/09/2020	No Data	-	-	-
16	16/09/2020	No Data	-	-	-
17	17/09/2020	I.D.	-	-	-
18	18/09/2020	54		Satisfactory	NO _x
19	19/09/2020	105		Moderate	PM _{2.5}
20	20/09/2020	316		Very Poor	PM _{2.5}
21	21/09/2020	577		Severe	PM _{2.5}
22	22/09/2020	694		Severe	PM _{2.5}
23	23/09/2020	598		Severe	PM _{2.5}
24	24/09/2020	39		Good	CO
25	25/09/2020	76		Satisfactory	PM ₁₀
26	26/09/2020	66		Satisfactory	PM ₁₀
27	27/09/2020	55		Satisfactory	PM ₁₀
28	28/09/2020	75		Satisfactory	PM ₁₀
29	29/09/2020	62		Satisfactory	PM ₁₀
30	30/09/2020	54		Satisfactory	PM ₁₀

I.D. – Insufficient Data